



Existing Conditions

Ⓐ The road network will be consolidated when site is fully managed by DEW. Site images and key locations visited.

Refer seperate Site Photos sheet.





Maize Island Lagoon Conservation Park Site Photos



Entry Signage.



Camping areas along river front.



View of cliff face across river.



Potential day use area.



Creek showing sand dune erosion.



Peter Jacobs Trail information sign at trailhead.



Peter Jacobs Trail.



Informal boat ramp.



Group camping area.

